EAST Search History

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	6944	(pad\$1 or lining\$1) near4 (electric\$4 adj conductiv\$5)	US-PGPUB; USPAT; USOCR	OR	OFF	2008/03/12 12:21
L2	14	brak\$3.ti. and (pad \$1 or lining\$1) near4 (electric\$4 adj conductiv\$5) and wear	US-PGPUB; USPAT; USOCR	OR	OFF	2008/03/12 12:22
L3	2	(("3553642") or ("4602702")).PN.	USPAT	OR	OFF	2008/03/12 13:22
L4	1	2 and powder\$2	US-PGPUB; USPAT; USOCR	OR	OFF	2008/03/12 13:24
L5	7	brak\$3.ti. and (pad \$1 or lining\$1) and (electric\$4 adj conductiv\$5) and wear and powder \$2	US-PGPUB; USPAT; USOCR	OR	OFF	2008/03/12 13:24
L6	45	("4602702").URPN.	USPAT	OR	OFF	2008/03/12 13:37
L7	46	brak\$3.ti. and (pad \$1 or lining\$1) near5 (pressure or force) and compar \$3 near6 values	US-PGPUB; USPAT; USOCR	OR	OFF	2008/03/12 13:47
L8	41	("3537551" "3582926" "3623576" "3730301" "3797612" "3810087" "3922640" "4020454" "4029859" "4241603" "4392202").PN. OR ("4591213").URPN.	US-PGPUB; USPAT; USOCR	OR	OFF	2008/03/12 13:51
L9	308	188/1.11L.ccls.	US-PGPUB; USPAT; USOCR	OR	OFF	2008/03/12 13:56

L10	367	188/1.11e.ccls.	US-PGPUB; USPAT; USOCR	OR	OFF	2008/03/12 13:56
L11	646	9 or 10	US-PGPUB; USPAT; USOCR	OR	OFF	2008/03/12 13:56
L12	3	11 and (copper adj powder or carbon adj black)	US-PGPUB; USPAT; USOCR	OR	OFF	2008/03/12 13:57
L13	26	188/251m.ccls. and (copper adj powder or carbon adj black)	US-PGPUB; USPAT; USOCR	OR	OFF	2008/03/12 14:06
L14	323	brak\$3.ti. and (pad \$1 or lining\$1) and wear and (pressure or force) near4 (transducer or sensor)	US-PGPUB; USPAT; USOCR	OR	OFF	2008/03/12 14:20
L15	53	14 and (pad\$1 or lining\$1) near4 (transducer or sensor)	US-PGPUB; USPAT; USOCR	OR	OFF	2008/03/12 14:21
L16	37	15 and (pad\$1 or lining\$1) near4 (force or pressure)	US-PGPUB; USPAT; USOCR	OR	OFF	2008/03/12 14:22

3/12/08 2:28:53 PM